

**Recall Date:** July 6, 2017

**Recall Number:** 17-753

Cub Cadet Recalls Utility Vehicles Due to Crash Hazard (Recall Alert)

### Recall Summary

**Name of Product:** Cub Cadet 2016 Challenger utility vehicles

**Hazard:** Air in the brake system can cause brake failure, posing a crash hazard to the user or bystander.

**Remedy:** Repair

Consumers should immediately stop using the recalled vehicles and contact an authorized Cub Cadet dealer or Cub Cadet customer service to arrange for a free repair.

**Consumer Contact:** Cub Cadet toll-free at 888-848-6038 from 8 a.m. to 8 p.m. ET Monday through Friday, 9 a.m. to 5 p.m. ET Saturday or Sunday, or online [www.cubcadet.com](http://www.cubcadet.com) and click on "Product Recalls" for more information.

### Recall Details

Units: About 4,000

#### Description:

This recall involves four-wheel drive Cub Cadet 2016 Challenger utility vehicles. Model numbers included in the recall are: CX500 (37AW7CKD010, 37AW7CKD710, 37AW7CLD010, 37AW7CLD710, 37AW7CMD710, 37AW7CND710); CX700 (37AX7CKD010, 37AX7CKD710, 37AX7CLD010, 37AX7CLD710, 37AX7CMD710, 37AX7CND710); and CX750 Crew(37AY8CKD710, 37AY8CLD710, 37AY8CMD710, 37AY8CND710). The utility vehicles were sold in yellow, red, blue and camouflage. The recalled vehicles were manufactured between March 2016 through November 2016. A label located under the driver's seat lists the model number and the month and year of manufacture.

#### Incidents/Injuries:

Cub Cadet has received 80 reports of brake failure. No injuries have been reported.

**Sold at:** Independent Cub Cadet dealers nationwide from March 2016 through May 2017 for between \$8,500 to \$9,500.

**Manufacturer(s):** Hisun Motors Corp. U.S.A., of McKinney, Texas

**Manufactured In:** China

